

## Menu


HISTORY FILE MAP for year 2001

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK



DSS14 repairs led to large gap in coverage. DSS54, DSS24 and DSS16 provided uplink for additional periods, & DSS25 provided downlink for monitoring during an uplink gap. Total of 35m RT data lost, 1h03m 15% degraded and 35m 92% degraded due to this improvised coverage. Thanks to all personnel involved for their assistance.